CERCLA D			Contract #:	EP-S9-12-01	Page 1 of 1	
Site Name Location/Region:	Maywood, CA	esium Fire Incident	Date:		6 2016	
ERRS:	Environmental Quality Mgmt		OSC:	Tuesday, July 26, 2016 Jason Musante		
START:	NA		USCG	NA		
OTAKT.	114/3	Description of Wa	ork to be Performe			
1 Most OCC to disc	de el meneratotion	· · · · · · · · · · · · · · · · · · ·	or to be I chomic	,		
1. Meet OSC to disc						
2. Drive to site, meet						
Begin pumping co	ntents of Baker Ta	ank into vac truck - t	wo loads today (a	oproximately 9300 gall	ons)	
4. Secure site when	complete					
		Number of Auth	norized Personnel			
Supervisors:	1	Operators:	1	FCA		
Foremen:		Technicians:	1	Truck Driver		
	Aut	horized Equipment a	and Expendable M	laterials		
Item		Quantity	Item		Quantity	
Car, economy		,	1			
			1			
Computer		+				
5000 gallon Vac Tru	ck (transporter)		2			
I certify that the above work is ordered and authorized by			1 '	above work is ordered	and authorized by	
the OSC in the abov				bove cited contract.		
JASUN MUSA		Peter.	Lawrence			
Signature of On-Sce	<u> </u>	Signature of Cor	ntractors Representativ			
olgitature of Ort-Occ	TIC COOldinator	Δmer	Idments	THACTOR'S PROPERTIES.		
		Aillei	idinents			
Signature of On-Scene Coordinator			Signature of Contractors Representative			